
Indiana Brownfields Conference Scribner Place

April 12, 2006

Presented by:
John Rosenbarger
New Albany Redevelopment &
Plan Commission Director












Scribner Place: North & East Elevation





Blue Plan




Tower Plan



Tower Plan



Scribner Place Site: 2005 Prior to Clean-up




ESA Environmental Site Assessment

Phase I Environmental Site Assessment (ESA)

Overview of Historic Site Environmental Conditions

- Record Searches Government Data Bases
- Historic City Directories Public Library
- Historic Aerial Photographs
- Historic Sanborn Fire Insurance Maps
- Interviews with Owners & Others
- Completed September 2002



ESA Historic Land Uses

Phase II Environmental Site Assessment (ESA)

Collection and Analyses of Soil Samples to Determine if Suspected Contaminants are Present

- 41 Total Soil Borings
- 2 Waste Samples
- Asbestos and Lead-based Paint Surveys
- Completed April 2003

Soil and Groundwater Investigation

Required by IDEM to demonstrate that groundwater has not been affected by historic activities

- 10 Groundwater Monitoring Wells
- Soil Samples every 2-feet throughout vertical column in vadose zone (non-saturated zone)
- Completed October 2003

Contaminants of Concern (COCs) Phase 1 Remediation – Scribner Place

COCs Detected in Soil	IDEM Industrial Default Closure Level (IDCL) mg/Kg (ppm)	Lowest Concentration >IDCL mg/Kg (ppm)	Highest Concentration >IDCL mg/Kg (ppm)
Arsenic	20	21.7	92
Lead	230	244	3390
Benzo(a)anthracene*	15	82	82
Benzo(a)pyrene*	1.5	1.9	55
Benzo(b)fluoranthene*	15	94	94
Chrysene*	25	70	70
Indeno(1,2,3-cd)pyrene*	3.1	4.0	43
Naphthalene*	170	230	230

^{*}Semi-volatile organics primarily detected next to former auto service building





State Street Elevation



Northeast Elevation

Interior Pools



Zero Depth Pool



The Finished Project



The Finished Project

